

02/19/2016

HOWARD ROICE NELSON 2155 WEST 700 SOUTH 31 CEDAR CITY UT USA 84720

Claim Number

Date of Loss

Balance Due

Renter's name

Rental Agreement#

: 08576828

: 01/15/2016

: \$1,570.41

: HOWARD ROICE NELSON

: 223798773

Dear Sir/Madam:

Our review indicates that you are responsible for the damages to our vehicle.

Enclosed please find documentation to support our claim. Please review this information and remit payment in full to the address above. Please include our claim number on your payment. If you prefer you may also pay the amount due using a debit card, credit card or directly from your bank account at

http://www.claimtopay.com

If you have reported this claim to your insurance and / or credit card company, please contact our office with the claim information.

If you have any questions, please contact us at the number below.

Sincerely,

ALAMO RENT A CAR

DAMAGE RECOVERY

Phone:

8663003239

Fax:

9189486635

Email:

DRU1@ehi.com



INVOICE

Date: 02/19/2016

HOWARD ROICE NELSON 2155 WEST 700 SOUTH 31

Claim #: 08576828 Unit #: 7LKM2F

Billing Invoice #: 3000339604

CEDAR CITY UT USA 84720

Vehicle Information

VIN: 5NPDH4AEXGH715862

Year: 2016 Make: HYUN Model: ELAN

Item	Total Cost	Amount Due
Damage	\$1,159.50	\$1,159.50
Sublet	\$3.00	\$3.00
Admin Fees	\$100.00	\$100.00
Loss of Use (12.8 / 4) hours @ \$59.99 per day @ 100% occupancy	\$191.96	\$191.96
Diminishment of Value	\$115.95	\$115.95

Total Amount Due: \$1,570.41*

*Remit payment in U.S. Dollars.

PAY UPON RECEIPT

ALL PAYMENTS MUST INCLUDE THIS REMITTANCE TO BE CREDITED PROPERLY!

PAYABLE TO: DAMAGE RECOVERY PO BOX 801770 KANSAS CITY MO USA 64180 Toll Free #: 8663003239

Claim #	F:	085/682	8
Unit #	#:	7LKM2	F
Billing Invoice #:	30	0033960	4

Total Amount Due: \$____ *Remit payment in U.S. Dollars.

1,570.41*

Total Amount Remitted: \$ _____



Estimate Information

Estimate ID: 3000643373

Estimator: File ID: 454 Platform: CCC Date Created: 01/18/2016

Claim: DX066HBI9

Repair Facility: Alex Body Shop Address: 11545 Bissonnet St Houston, TX 77099

Phone: 281-5068530

Fax:

Federal Tax ID: 45-4904339

State Tax ID: BAR:

Vehicle Data

Unit #: 7LKM2F

Make: Hyundai

Repair Facility

Model: ELANTRA SE

VIN: 5NPDH4AEXGH715862 Body Style: 4D SED

Color: Engine:

Year: 2016

Lic. State: Odometer:

License: Prod. Date:

Point of Impact

Primary: Unknown Point of Impact Secondary: Unknown Point of Impact

Line	The H								
Line	Op	Description	Type	Part#	Price	Qty	Labor	Paint	Labor Amt
001		FRONT BUMPER							
002*	RI	R&I bumper cover 1/2					0.6B		\$18.00
003		FENDER					-		410.00
004*	BLND	RT Fender						1.1R	\$33.00
005		FRONT DOOR							Ψ33.00
006*	RR	RT Door shell -20%	N	760043X500	\$631.90	1	5.2B	3R	\$246.00
007	BLANK	Add for Clear Coat						1.2R	\$36.00
008		REAR DOOR						1.210	Ψ30.00
009	BLND	RT Door shell from 10/29/10						1R	\$30.00
010	RI	RT Belt molding w/o chrome					0.3B		\$9.00
011	RI	RT Handle, outside w/o chrome					0.4B		\$12.00
012*	SUB	Hazardous waste removal			\$3.00		OB		
013*	RR	Cover Car			\$5.00		0B		
Totals									

Parts				
Part	SubTotal	Adj%	Adj\$	Total
Parts - New	\$789.88	0	(\$157.98)	\$631.90
				\$631.90

Additional Labor	Rate	Hours	Total
	\$30.00	6.3	\$189.00
	\$30.00	6.5	\$195.00
			\$384.00
	Additional Labor	\$30.00	\$30.00 6.3

Materials - 2 Stage Paint Materials	\$26.40
Materials - Blend	\$46.20
Materials - Paint	\$66.00
	\$138.60

Miscellaneous	
Other - Additional Cost	\$5.00
Other - Sublet	\$3.00
	\$5.00

Adjustment	
Total Claim Before Taxes	\$1,162.50
Total Transaction Amount	\$1,162.50
Insurance Pay	\$1,162.50
	\$1,162.50



Op Codes			
RREP	Operation - Remove and Repair		
R1ST	Operation - Repair First, else Replace		
REDO	Operation - Redo		
CG	Operation - Chip Guard		
TT	Operation - Two Tone		
PDR	Operation - Paintless Dent Repair		
RPR	Operation - Repair		
PRPR	Operation - Repair, Partial		
RR	Operation - Remove/Replace		
RRP	Operation - Remove/Replace, Partial		
ADC	Operation - Additional Costs		
ADO	Operation - Additional Operations		
BLND	Operation - Blend		
SUB	Operation - Sublet		
RPD	Operation - Related Prior Damage		
AA	Operation - Appearance Allowance		
BLANK	Operation - Blank		
RFRP	Operation - Refinish/Repair		
` RI	Operation - Remove/Install		
ARP	Operation - Additional Repair		
ALGN	Operation - Alignment		
O/H	Operation - Overhaul		
REF	Operation - Refinish		
INSP	Operation - Inspect		
C/AJ	Operation - Check/Adjust		
UPD	Operation - Unrelated Prior Damage		
RI	Operation - Remove and Reinstall		
Part Type Codes			
A	Parts - Aftermarket		
C	Parts - Re-chromed		
Е	Parts - Existing		
L	Parts - Recycled		
M	Parts - Remanufactured		
N	Parts - New		
P	Parts - New, partial		
R	Parts - Re-cored		
GL	Glass		
	Labor Codes		
R	Labor - Refinish		
S	Labor - Structural		
U	User Defined Labor		
U	User Defined Labor 1		
U	User Defined Labor 2		
U	User Defined Labor 3		
U	User Defined Labor 4		
В	Labor - Body		
D	Labor - Diagnostic		
Е	Labor - Electrical		
F	Labor - Frame		
G	Labor - Glass		
M	Labor - Mechanical		















